

General Environmental Incident Summary

Incident: 4061 **Date/Time Notice:** 4/6/2016 1610 **DEM Incident No:**
Responsible Party: Minot AFB
Date Incident: 4/5/2016 **Time Incident:** 2000 **Duration:** 12 hours
County: McLean **Twp:** 149 **Rng:** 88 **Sec:** 27 **Qtr:** SW SW
Lat: 47.68949 **Long:** -101.93440 **Method:** Interpolation from map
Location Description: Minot AFB Missile Site E-09

Submitted By: Michael Getty **Affiliation:** Chief, Environmental Management
Address: 5 CES/CEIE
445 Peacekeeper Place
City: Minot AFB **State:** ND **Zip:** 58705

Received By:

Contact Person: Michael Getty
201 Summit Drive
Minot AFB, ND 58705

Distance Nearest Occupied Building: 15 Miles **Release Contained:** Yes

Type of Incident: hydraulic fluid leak

Description of Released Contaminant: hydraulic fluid

Volume Spilled: 20.00 gallons **Ag Related:** No

EPA Extremely Hazardous Substance: No **Reported to NRC:** Yes

Cause of Incident:

Malfunction of hydraulic cylinder on missile transport erector

Risk Evaluation:

None

of Fatalities: 0 **# of Injuries:** 0 **Affected Medium:** 03 - soil

Potential Environmental Impacts:

None

Action Taken or Planned:

Contained with pig mat, soil excavated. Contaminated material was containerized and transported to Minot AFB HazMart for compliant disposal

Wastes Disposal Location: Contaminated material will be transported to Minot AFB for transport to a regulatory compliant disposal facility

Agencies Involved:

Updates

Date: 4/6/2016 ***Status:*** Reviewed - No Action Required

Author: Crowdus, Kory

Updated Volume:

Notes:

Spoke to contact who indicated that release was inside the fenced area of missile site and was cleaned up immediately. Soil was excavated and taken for proper disposal. No follow-up required.